

ND-1A Test Pits

Test Pit#1

Test Pit#2



Test Pit #1 is 60" deep and after 12' of overburden is tan colored clay with some fines. Material appears tightly packed and seems to be good load bearing material during the dry season.





Sample of Test Pit #1 clay. All test pits were dug on 7/31/19 in the dry season.





Test Pit #2 has about 12" material over what appears to be darker soils from organic breakdown





Darker material changed to a tan color at 60". It does not appear to carry the same load as Pit #1





Test Pit #2 is 60".

